

SERVICE BULLETIN



No. : 0IVL20060063

Date : 2006-06-20

Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	Model No.
	EKHQ	26LX1D-UA	ALUSLL	26LX1D-UA	ENMX	26LX1D-UA	ALUSLL	26LX1D
	EKHQ	26LX2D-UA	ALUSLL	26LX2D-UA	ENMX	26LX2D-UA	ALUSLL	26LX2D
	EKHQ	32LP1D-UA	ALUSLL	32LP1D-UA	ENMX	32LP1D-UA	ALUSLL	32LP1D
	ENMX	32LP1D-UA	APUSLT	32LP1D	EKHQ	32LX1D-UA	ALUSLL	32LX1D-UA
	EKHQ	32LX1D-UA	APUSLL	32LX1D	ENMX	32LX1D-UA	ALUSLL	32LX1D
	ENMX	32LX1D-UA	APCALL	32LX1D	ENMX	32LX1D-UA	APCALT	32LX1D
	ENMX	32LX1D-UA	APUSLT	32LX1D	EKHQ	32LX2D-UA	ALUSLL	32LX2D-UA
	ENMX	32LX2D-UA	ALUSLL	32LX2D	ENMX	32LX2D-UA	APUSLT	32LX2D
	EKHQ	37LP1D-UA	ALUSLL	37LP1D-UA	ENMX	37LP1D-UA	ALUSLL	37LP1D
	ENMX	37LP1D-UA	APUSLL	37LP1D	EKHQ	42LP1D-UA	ALUSLL	42LP1D-UA
	ENMX	42LP1D-UA	ALUSLL	42LP1D	ENMX	42LP1D-UA	APUSLL	42LP1D
Buyer	Buyer Name	Buyer Code	Buyer Name	Buyer Code	Buyer Name	Buyer Code		
	LGEUS	US000001	LGEAI	US000002				
EFFECTIVE DATE	2006-06-20		EFFECTIVE FROM(SERIAL NO.)		All serial No.			
Subject	To stop a fan of DCR model(LCD DTV) when TV is off.							
No.	Loc No.	Before Change		After Change		Note	K-Code	Remark
		Part No	DESC./SPEC.	Part No	DESC./SPEC.			
Reason Of Change								
DCR_FAN.pdf								

** FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

NOTE(**) : INTERCHANGEABILITY CODE				KEY-WORD CODE
	Parts	Set		
A	Original	Early		1. To improve performance 2. To improve productivity
	New	Late		
B	Original	Early		3. To improve reliability 4. Change of material or dimension
	New	Late		
C	Original	Early		5. Addition 6. Deletion
	New	Late		
D	Original	Early		7. Correction
	New	Late		

CHIEF ENGINEER , *approved*
 Factory.